



**LEGEND :**  
 ● SD - SMOKE DETECTOR  
 ■ CMA - CARBON MONOXIDE ALARM

**DRYER EXHAUST NOTE:**  
 A. DRYER MOISTURE EXHAUST DUCT VENT SHALL HAVE A MAX HOR. AND VERT. LENGTH OF 14' INCLUDING TWO-90 DEG ELBOWS. THE DUCT SHALL BE EQUIPPED WITH A BACK DRAFT DAMPER AND HAVE MIN DIA 4". THE VENT DISCHARGE SHALL BE MIN. 3' AWAY FROM ANY BUILDING OPENING.

**PLUMBING FIXTURE UPGRADE NOTES:**  
 A. WATER CLOSETS WITH A FLOW RATE IN EXCESS OF 1.6 GFP WILL NEED TO BE REPLACED WITH MAX FLOW OF 1.28 GFP  
 B. SHOWER HEADS WITH A FLOW RATE GREATER THAN 2.5 GPM WILL NEED TO BE REPLACED WITH A MAX 2.0 GPM.  
 C. LAVATORY AND KITCHEN FAUCETS WITH A FLOW RATE GREATER THAN 2.2 GPM WILL NEED TO BE REPLACED WITH MAX FLOW RATE OF 1.5 GPM. (OR 1.8 GPM FOR KITCHEN FAUCETS).



**Owner** JENNY SUI  
 3014 BAYO VISTA  
 ALAMEDA, CA. 94501  
 T:  
**Designer** JOSEPH A LANDRY  
 2834 ADAMS ST  
 ALAMEDA CA 94501  
 T: (510) 381-4159

**3014 BAYO VISTA**  
 ALAMEDA, CA  
 94501

Rev. Date    Remarks  
 07/07/17    BUILDING REVIEW COMMENTS

Date: 04/13/17  
 Scale: AS NOTED  
 Project Name: JENNY SUI ALAMEDA, CA  
 Project No. 020117

Drawing Title:  
**NEW SECOND FLOOR PLAN**  
 Sheet No. **A-2.3**